





burn-through defects caused by the increase in arc force. In other words, the defects are a result of current increased to compensate the lack of leg length due to increased welding speed. The current also needs to be increased to bridge inevitable root gaps





